

4156A-05

S E R V I C E N O T E

SUPERSEDES: None

**HP 4156A Precision Semiconductor Parameter Analyzer**

Serial Numbers: JP10A00101 / JP10A00138

**Push button keys stick in the front panel**

To be Performed by: HP-qualified personnel

**Parts Required:**

HP P/N	Qty	Description
04155-40003	1	Front Keys
04156-65101	1	Front Panel

**Situation:**

The push button keys may stick in the front panel, or may not stick out enough from the front panel.

**Solution/Action:**

Replace the Front Keys and Front Panel.

DATE: October 1994

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 1.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> HP LOCATION	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	HP RESPONSIBLE UNTIL: October 1997	
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		
AUTHOR: MN	ENTITY: 3301	ADDITIONAL INFORMATION:	

