

S E R V I C E N O T E

SUPERSEDES: NONE

AGILENT 4263B LCR Meter

Serial Numbers:MY40100101 / MY40100233

Measurement accuracy may be out of specification**To Be Performed By:** Agilent-Qualified Personnel**Parts Required:** Not used**Situation:**

Units given serial number above may not meet its measurement accuracy specification due to mis-calibration at factory. All units in the range given above should be re-calibrated at service center immediately.

Solution / Action:

Perform all adjustments. And do performance test and functional check to verify instrument operation.

DATE: January 2001

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	<input checked="" type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 2.0 Hours		
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: January 2002		
AUTHOR: HAM	ENTITY: 3355	ADDITIONAL INFORMATION: Using O2G for the Repair Class and enter the Service Note # in the Repair Details SIS-Entry			

