

4935A - 17A

S E R V I C E N O T E

SUPERSEDES: 4935A-17

HP 4935A Transmission Impairment Measuring Set

Serial Numbers: 0000A00000 / 9999A99999

Volume Control Pot/A2R36

Volume Control Assembly for Older Instruments

Situation:

The vendor for the volume control pot, p/n 2100-3858, will no longer be manufacturing this part. A replacement for the 2100-3858 was found that has a different lead pattern. This required a relayout of the A2 board to accommodate this new part. For older switch boards that will not accommodate the new part, volume control assemblies have been designed to use as a replacement for 2100-3858.

Solution/Action:

New volume control assemblies have been designed for the 04935-60002 and the 04935-60027 (Rev A & B & C) switch boards. Order the replacement part according to the part number of the switch board in the instrument when replacing the A2R36, volume control pot.

Continued

DATE: 04 May 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

RCB

3800

© 1994 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.



Switch Board P/N	Volume Control Replacement
04935-60002	04935-62906
04935-60102	04935-62906
04935-60027 (Rev A & B)	04935-62907
04935-60027 (Rev C)	2100-3924