SERVICE NOTE

SUPERSEDES

HP 4936A Transmission Impairment Measurement Set

Serial Numbers: 0000U00000/9999U99999

Replacement Battery Packs

Situation

When replacing the HP 4936A battery, the parts needed are serial number dependant.

Solution/Action:

For serial numbers 2916U02971/9999U99999 order battery pack 04935-62904.

For serial numbers 0000U00000/2916U02970 a number of items are needed to accommodate the new improved battery pack 04935-62904. Order the following if the battery needs to be replaced:

| Description | Part Number | Qty |
|-------------------|-------------|-----|
| Battery | 04935-62904 | 1 |
| Battery Insulator | 04935-45401 | 1 |
| Cable Tie | 1400-0307 | 1 |
| Screw | 2510-0043 | 4 |
| Washer (flat) | 3050-0001 | 4 |
| Shield Support | 04936-00004 | 1 |

Continued

DATE: 26 May 1992

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: INFORMATION ONLY | | |
|--|---------|-------------------------|
| AUTHOR: | ENTITY: | ADDITIONAL INFORMATION: |
| S.L. | 1400 | |
| | | |
| | | |

© 1992 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.



Page 2 Service Note 4936A-16

Assembly Notes:

1. When changing the shield support, re-use the 6 screws which secure the A3 assembly.

- 2. Place the battery assembly and the insulator onto the shield support and fix with the screws and washers provided.
- 3. Once assembled, charge the unit for 17 hours.