

S E R V I C E N O T E

SUPERSEDES: None

5087A Distribution Amplifier**Serial Numbers:** 0000A00000 / 2208A06294

C1 on Heat Sink Assembly (0180-2188)

Replacement of Obsolete Electrolytic Filter Capacitor**To Be Performed By:** Agilent-Qualified Personnel**Parts Required:** 5063-2341 Capacitor and 05087-90009 Installation Note**Situation:**

Part number 0180-2188 has been obsoleted and can no longer be supplied. A replacement assembly 5063-2341 has been developed to replace 0180-2188 with minor modification.

Solution:

When it has been determined that C1 has failed and 0180-2188 is not available, 5063-2341 can be installed in its place by enlarging one of the four mounting slits to accept a 6-32 screw and washer. Step-by-step instructions are listed, if necessary, in Installation Note 05087-90009.

DATE: June 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

CF

0200

