

64145A-01

S E R V I C E N O T E

SUPERSEDES: None

HP 64145A/AL/B/BL/C/CL/D/DL/F 7700 Series Emulator

Serial Numbers: 3101J00001 / 3101J00107

Duplicate Service Notes: None

Recommended ROM Kit to fix incorrect trace of SEB instruction

To Be Performed By: HP-Qualified Personnel

Parts Required:

HP Part No.	Qty.	Description
64145-68702	1	SEB ROM Kit

Situation:

The emulator disassembles SEB instructions incorrectly in trace listing

Solution/Action:

Replace the following ROM with the one in the ROM Kit.

- U317 (64145-85001) on 7700 CPU Board (64145-66501).

DATE: 21 October 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR: 1.00 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input type="checkbox"/> HP LOCATION	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	RESPONSIBLE ENTITY: 3300	UNTIL: 01 November 1993
AUTHOR: HM	ENTITY: 3301	ADDITIONAL INFORMATION:	

