

MODIFICATION AVAILABLE – PERFORMANCE ENHANCEMENT
 CHARGEABLE TO CUSTOMER SERVICE / RELIABILITY
 ENHANCEMENT CHARGEABLE TO CONTRACT IF THERE IS ONE.

81101A-04C

S E R V I C E N O T E

Supersedes:
 81101A-04B

81101A Pulse Generator

Serial Numbers: DE38900332 / DE41B01983
 (All units with Firmware Rev. 01.02.00 to Rev. 01.11.00)

New Firmware 01.12.01 / BIOS 1.30 package available

To Be Performed By: Customer

Parts Required:

P/N	Description	Qty.
0950-3380	1 MB SRAM PCMCIA memory card	1
1819-0083	2 MB SRAM PCMCIA memory card	1

or equivalent (5 V SRAM cards without attribute memory)

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	AGREEABLE TIME	x PERFORMANCE ENHANCEMENT <input type="checkbox"/> SERVICE / RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	x CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	AVAILABLE UNTIL: Product's Support Life
AUTHOR: SM PRODUCT LINE: 24		
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2005
 PRINTED IN U.S.A.



February 17, 2005

Situation:

Several bugs have been fixed with this new Firmware / BIOS bundle. Additionally, a new GPIB commands allow to program a delay for the switching of the output channel relays, reducing possible glitches or spikes at switching on a channel in triggered mode.

Solution/Action:

The software package is customer installable via GPIB. A self-extracting archive, including documentation about the new GPIB commands and installation instructions can be downloaded from the “Software & Firmware Downloads” section of

http://www.agilent.com/find/pulse_generator