

81133A-02

S E R V I C E N O T E

Supersedes:
NONE

81133A – High Speed Pulse Generator

Serial Numbers: “ALL”

81133/34A Firmware Version 2.95 Update available

Parts Required:

P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY::	AGREEABLE TIME	X PERFORMANCE ENHANCEMENT X SERVICE / RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE [] ON-SITE X SERVICE CENTER [] CHANNEL PARTNERS	AVAILABILITY:12/01/2012
AUTHOR: FK		PRODUCT LINE: 24
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2011
PRINTED IN U.S.A.

December 15, 2011

Rev. 18



Situation:

Starting December 2011 channel modules with a new revision of hybrid amplifier chips are shipped which feature a new HW ID together with BIOS 1.20 and require a new FW version 2.95 to be supported.

Solution/Action:

The firmware package 2.95 is customer installable via GPIB, USB or LAN. An archive, including documentation with installation instructions can be downloaded from the Agilent homepage:

<http://www.agilent.com>