

81150A-04

S E R V I C E N O T E

Supersedes:
NONE

81150A Pulse Function Arbitrary Noise Generator

Serial Numbers: ALL

Front panel USB connector does not work anymore, however the USB connector on the back still works.

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: HK	PRODUCT LINE: PL24
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2008
PRINTED IN U.S.A.


October 6, 2008

Rev. 15




Situation:

The USB connector on the front panel of the 81150A is not working. The next picture shows the front panel USB connector.



The USB connector on the back is still working. The next picture shows the USB connector on the back (the left one with the red circle).

**Solution/Action:**

There is a failure on the mainboard and it needs to be replaced.

The part numbers for the 1 channel unit

- 81150-60501 Replacement kit
- 81150-69501 Exchange kit

The part numbers for the 2 channel unit

- 81150-60502 Replacement kit
- 81150-69502 Exchange kit