

S E R V I C E N O T E

SUPERSEDES: NONE

83236B PCS Interface Rear Plate**Serial Numbers:** 3711J05834 / 3711J06004**Incorrect label for the EXT TRIG IN terminal.****To Be Performed By:** Customer or Agilent-Qualified Personnel**Parts Required:**

Agilent P/N	Description	Quantity
none	EXT TRIG IN label	1

Situation:

It has been found that instruments with the given serial number have a incorrect label for the EXT TRIG IN terminal on the Rear Plate. Correct terminal name is EXT TRIG IN, label shows "EXT TRIG".

Solution / Action:

Use label to cover incorrect rear panel EXT TRIG marking. To get the EXT TRIG IN label, send a mail to "SVC-SUPPORT_KOBEWT@agilent.com" with nyour ame and address.

DATE: April 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY: AGREEABLE TIME		<input type="checkbox"/> PERFORMANCE ENHANCEMENT <input checked="" type="checkbox"/> SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	AVAILABLE UNTIL: April 2003
AUTHOR: SA	ENTITY: 3355	ADDITIONAL INFORMATION:

