

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**83623A-08**

# S E R V I C E N O T E

Supersedes:  
None

## Agilent 83623A - 8360 Series Synthesized Sweeper

**Serial Numbers:** [0000A00000 / 9999Z99999]

**A23 10 MHz Reference replacement part number change.**

**Parts Required:**

| P/N         | Description         | Qty. |
|-------------|---------------------|------|
| 10811-60126 | Quartz Crystal Osc. | 0    |
| 1813-1258   | OCXO 10 MHz Prec.   | 1    |

## ADMINISTRATIVE INFORMATION

|                                     |
|-------------------------------------|
| SERVICE NOTE CLASSIFICATION:        |
| <b>INFORMATION ONLY</b>             |
| AUTHOR: DMc      PRODUCT LINE: PL15 |
| ADDITIONAL INFORMATION:             |

© AGILENT TECHNOLOGIES, INC. 2002  
PRINTED IN U.S.A.

August 7, 2002



**Situation:**

The design of part number 10811-60126 has changed and should not be ordered as a replacement for the 8360 Series. The 10811-60126 power supply design has changed from constant impedance to constant power. This change causes a current spike at turn-on that can activate the +22 V current limiting circuit on the A16 Post Regular in the 8360 Series.

**Solution/Action:**

When replacing an A23 10 MHz Reference oscillator, order part number 1813-1258, do not order part number 10811-60126.