

## S E R V I C E N O T E

SUPERSEDES: NONE

**8517A S-Parameter Test Set**

Serial Numbers: 0000A00000 / 9999Z99999

**Test Set Option 002 deletion**

Duplicate Service Notes: 8517B-02

To Be Performed By: Agilent-Qualified Personnel

**Parts Required:**

P/N	Description
08517-60047	Service Kit

**Situation:**

8517A Test Set option 002 deletes the attenuators and the bias TEEs.

**Solution/Action:**

8517A Test Set with option 002 can be retrofitted into standard test set by installing the service kit 08517-60047. The kit contains the necessary parts and instructions to install the kit properly.

DATE: January 1997

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR 5.0 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		
AUTHOR: JZ	ENTITY: 5340	AGILENT RESPONSIBLE UNTIL: Product's SupportLife	
		ADDITIONAL INFORMATION:	