

86100B-03

S E R V I C E N O T E

Supersedes:
None

86100B Infiniium DCA Wide Bandwidth Oscilloscope

Serial Numbers: 0000A00000/9999Z99999

Repair the 86100B A18 ATX Power Supply Interface Board Assembly to the Component Level

Parts Required:

P/N	Description	Qty.
-----	-------------	------

Contact the DSA Factory Support Team

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: DL	PRODUCT LINE: 8F
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2007
PRINTED IN U.S.A.



October 23, 2007

Situation:

The A18 ATX Power Supply Interface board assembly should be repaired to the component level due to board assembly supply issues.

Solution/Action:

When possible, repair the A18 board assembly to the component level. Contact the DSA support team if there are any questions.