

DAYTON

ELLIS DONNIE R

S E R V I C E N O T E

8690A-13

Supersedes:

NONE

**HP MODEL 8690A SWEEP OSCILLATOR**

**All Serials**

**RECOMMENDED REPLACEMENT FOR A8C4 AND A8C5**

The recommended replacement for A8C4 and A8C5 in all 8690A Sweep Oscillators is HP Part Number 0160-4051. The 0160-4051 has the same capacitance value and is a direct replacement. The capacitor supports on the printed circuit board are not needed for the replacement capacitor and can be discarded.

No recalibration is necessary.

Correct your 8690A Operating and Service Manual Parts List to reflect the above changes.

AS/RH/WN

3/74-45

HEWLETT  PACKARD

For more information, call your local HP Sales Office or East (201) 265-5000 • Midwest (312) 677-0400 • South (404) 436-6181 • West (213) 877-1281. Or, write: Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304. In Europe, Post Office Box 85, CH-1217 Meyrin 2, Geneva, Switzerland. In Japan, Yokogawa-Hewlett-Packard, 1-59-1, Yoyogi, Shibuya-Ku, Tokyo, 151.

Printed in U.S.A.