

HP MODEL 8691-7A/B R. F. UNITS

All Serials

RECOMMENDED REPLACEMENT TRANSISTOR

The recommended replacement transistor for A1Q2 in all 8690A R. F. Units is HP Part Number 1853-0020.

The new transistor has a higher breakdown voltage. A1Q2 should only be replaced if the original transistor fails.

9/67-4

