

## S E R V I C E N O T E

SUPERSEDES: None

**E2500B Frequency Agile Signal Simulator (8791 Model 11)****Serial Numbers:** 3105A00101 / 3109A00117**Addition of Board Holder to the 11780B Smart Interface****To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

<b>Part No.</b>	<b>Qty.</b>	<b>Description</b>
11780-60104	1	Board Holder Kit

The 11780-60104 kit consists of the following parts:

<b>Part No.</b>	<b>Qty.</b>	<b>Description</b>
11780-90009	1	Installation Note
0515-0430	2	SCR - Mach M3.0 X 0.5
0515-0433	3	SCR - Mach M4.0 X 0.7
11780-00002	1	BD HLDR - TOP
11780-00003	1	BD HLDR - SIDE

*Continued*

DATE: 30 October 1991

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**MODIFICATION AVAILABLE**

ACTION CATEGORY:	AGREEABLE TIME	<input type="checkbox"/> PERFORMANCE ENHANCEMENT <input checked="" type="checkbox"/> SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	AVAILABLE UNTIL: 01 November 1992
AUTHOR: DGS	ENTITY: 0400	ADDITIONAL INFORMATION:

**Situation:**

During shipment of the E2500B Frequency Agile Signal Simulator, it has been determined that printed circuit boards may become unseated due to mechanical vibration during shipment.

**Solution/Action:**

Installing the above kit (part number 11780-60104) will prevent the boards from coming unseated due to mechanical vibration of the 11780B Smart Interface.