

MODIFICATION RECOMMENDED

E2676A-01

**S E R V I C E N O T E**

Supersedes:

E2676A Single Ended Browser

Serial Numbers: Product is not serialized

All black and early vintage gray nose cones or tips can crack or break

Parts Required:

| P/N         | Description          | Qty. |
|-------------|----------------------|------|
| 01130-60007 | Single Ended Browser | 1    |

ADMINISTRATIVE INFORMATION

|   |   |  |   |
|---|---|--|---|
| SERVICE NOTE CLASSIFICATION:  |   |  |   |
| <b>MODIFICATION RECOMMENDED</b>   |   |  |   |
| ACTION CATEGORY:  | <input checked="" type="checkbox"/> ON SPECIFIED FAILURE<br><input type="checkbox"/> AGREEABLE TIME   | STANDARDS  | LABOR: 0.5 Hours  |
| LOCATION CATEGORY:  | <input type="checkbox"/> CUSTOMER INSTALLABLE<br><input type="checkbox"/> ON-SITE<br><input checked="" type="checkbox"/> SERVICE CENTER<br><input type="checkbox"/> CHANNEL PARTNER | SERVICE INVENTORY: <input type="checkbox"/> RETURN<br><input type="checkbox"/> SCRAP<br><input checked="" type="checkbox"/> SEE TEXT | USED PARTS: <input type="checkbox"/> RETURN<br><input type="checkbox"/> SCRAP<br><input checked="" type="checkbox"/> SEE TEXT |
| AVAILABILITY:   | PRODUCT'S SUPPORT LIFE  | NO CHARGE AVAILABLE UNTIL: July 1, 2012  |   |
| AUTHOR:   | KO  | PRODUCT LINE: PL1A   |   |
| ADDITIONAL INFORMATION: This service note replaces the older E2676A-0304-01 |   |  |   |

© AGILENT TECHNOLOGIES, INC. 2009  
PRINTED IN U.S.A.

January 21, 2009

Rev. 16



**Situation:**

Due to a possible material or manufacturing defective, the nose cones where the resistors connect to the E2676A may crack or break. Not all E2676As will crack or break.

**Solution/Action:**

Service center must verify that the E2676A is cracked or broken before replacing. If the browser is not cracked or broken, it should not be replaced. Most browsers will never fail.

Replace only defective E2676As with black nose cones with the newer vintage E2676As with gray nose cones. The newer vintage E2676As have a date code after week 7520

Replace only defective older vintage E2676As with gray nose cones with E2676As with a date code after week 7520.

If you have a defective E2676A with a date code of 7520 or later, contact [support\\_col@agilent.com](mailto:support_col@agilent.com) or call 719-590-5801.

Directions to decode the browser date code.

There is a white label attached to one lead of the browsers.

Y2 W2 W1 Y1

Where Y1 = first digit of year

Where Y2 = second digit of year

Where W1 = first digit of week

Where W2 = second digit of week

Date code of 6700 is week 7 of 2006.

Date code of 7520 is week 25 of 2007.