

S E R V I C E N O T E

SUPERSEDES: NONE

E2929A PCI-X Master Target Test Card, 133MHZ

Serial Numbers:DE40300101 / DE40300158

Modification improves Power-Up Behavior**To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

The required material will be sent directly to the Service Center from the Division.

Situation:

The E2929A does not start in PCI-X mode in some systems.

Solution / Action:

Replace the part U110 on the E2929A with the Diode 1906-0358. Visit the URL

'http://wwwbvs.germany.agilent.com/pl24/marketing/webcoe/intern
'E2920A/Mode/Mode.html' for further information.

DATE: November 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR 0.5 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		
AUTHOR: RS		ENTITY: B100	
ADDITIONAL INFORMATION:			

