

## S E R V I C E N O T E

SUPERSEDES: None

**HP E4250A acceSS7 Signaling Monitoring System****HP E4251A acceSS7 Measurement Cardcage****HP E4258A acceSS7 External Communications Card****Serial Numbers:** 0000U00000/3608U01000**Compatability With E4270A Datastore SSP / E4506A Datastore Card****Situation:**

The original E4258A External Communications Card (Xcomms) firmware is not compatible with the E4506A DataCapture Card. (Xcomms Firmware Version A.01.20, ROM labeled "E4258-80001").

The Xcomms card reports "Invalid Cardcage Configuration" at self test if the E4506A Data-Capture Card is installed. The DataCapture Card is unusable.

*Continued*

DATE: March 1997

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR:

GC

ENTITY:

E600

ADDITIONAL INFORMATION:

**Solution/Action:**

If installing E4506A DataCapture Card, confirm the Xcomms firmware version is A.01.44 or later. (Xcomms Firmware Version A.01.44, ROM labeled "E4258-80003").

If the ROM is not labeled, verify the Xcomms firmware version using the E4251A acceSS7 Test Shell or acceSS7 Diagnostics, refer acceSS7 documentation. Verify Xcomms card firmware version is A.01.44 or later.

New Xcomms ROMs are shipped with E4506A DataCapture Card. Install this ROM into Xcomms card using the Install Instructions supplied.

If DataCapture Card is moved from Cardcage to Cardcage, confirm that the firmware version of Xcomms Card at the new location is A.01.44 or later. (Xcomms Firmware Version A.01.44, ROM labeled "E4258-80003").