

INFORMATION ONLY

E4438C-25

S E R V I C E N O T E

Supersedes:
NONE

E4438C Vector Signal Generator

Serial Numbers: ALL

False failure of Digital Mod PLA test on firmware rev C.05.81

Parts Required:

P/N	Description	Qty.
None		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
<input type="checkbox"/> Calibration Required <input checked="" type="checkbox"/> Calibration NOT Required	PRODUCT LINE: 15 AUTHOR: PY
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2014
PRINTED IN U.S.A.

April 16, 2014

Rev. 22



Agilent Technologies

Page 1 of 2

Situation:

The Digital Mod PLA Performance Verification will fail when ran on the TME if the instrument is with firmware 5.81.

Solution/Action:

Upgrade firmware to the latest, at the time of posting it's C.05.84.

Revision History:

Revision Number	Date	Author	Reason For Change
1.0	14-Apr-14	Petrina Yong	As published