

MODIFICATION RECOMMENDED

E8361C-01A

S E R V I C E N O T E

Supersedes:
E8361C-01

E8361C Option 014 PNA Microwave Network Analyzers

Serial Numbers: ALL

A guard is available to protect the front-panel jumper cables during shipment.

Parts Required:

| P/N | Description | Qty. |
|-------------|----------------------|-------------|
| E8361-00009 | Guard, jumper cables | 2 |

ADMINISTRATIVE INFORMATION

| | | | |
|---|--|--|-------------------|
| SERVICE NOTE CLASSIFICATION: | | | |
| MODIFICATION RECOMMENDED | | | |
| ACTION CATEGORY: | X AGREEABLE TIME | STANDARDS | LABOR: 0.25 Hours |
| LOCATION CATEGORY: | X CUSTOMER INSTALLABLE X ON-SITE X SERVICE CENTER X CHANNEL PARTNER | SERVICE INVENTORY: N/A | USED PARTS: N/A |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | NO CHARGE AVAILABLE UNTIL: END OF PRODUCT'S SUPPORT LIFE | |
| AUTHOR: | MF | PRODUCT LINE: WN | |
| ADDITIONAL INFORMATION: This Service Note applies to the following PNA models: E8361/3/4A Option 014, E8363/4B Option 014, E8363/4BH85 Option 014, E8361/3/4C Option 014, E8363/4CH85 Option 014, N5230A Options 425 & 525, and N5230C Options 425 & 525. | | | |

© AGILENT TECHNOLOGIES, INC. 2009
PRINTED IN U.S.A.

September 3, 2009

Rev. 16



Situation:

A guard is available to protect the front-panel jumper cables from being damaged during shipment.

Solution/Action:

Two guards should be installed to cover the front-panel jumper cables before the PNA is returned to the customer. The guards are identical, so either one can be used to cover the left or right-side jumper cables. The guards simply require a push-on installation, so no tools are necessary. To install, push each guard over the jumper cables until its cushioning material touches the front panel of the PNA.