

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**SN J6817A-02**

# S E R V I C E N O T E

Supersedes:  
NONE

## **J6817A E1 (75 Ohm BNC connectors) LIM**

**Serial Numbers:** [0000A00000 / 9999Z99999]

Due to the low volume sales of the A version of this product, it was determined that support assemblies for would not be set up with GTLS. Should the PCA's need to be replaced please use the equivalent B model boards. New (5067-0328) Exchange (5067-0084)

### **Parts Required:**

<b>P/N</b>	<b>Description</b>	<b>Qty.</b>
NONE		

## **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR: DM     PRODUCT LINE: 2J

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2003  
PRINTED IN U.S.A.



**Agilent Technologies**

July 18, 2003