

L4491A-01**S E R V I C E N O T E**Supersedes:
NONE**L4491A 4U RF/Microwave Switch Platform****Serial Numbers: MY00000000 - MY48000146****34945EXT modules purchased after June 1, 2008 require L4491A mainframe firmware revision 2.33 or greater.****Parts Required:**

P/N	Description	Qty.
-----	-------------	------

NONE

Situation:

34945EXT modules purchased after June 1, 2008 has new microprocessor that needs L4491A mainframe firmware version 2.33 or greater in order to work.

Solution/Action:

Update the mainframe firmware to version 2.33 or greater by following the procedure in Chapter 3 “Software Installation and Configuration” under “Firmware and Driver Updates” section of the [L4490A/L4491A RF Switch Platform User’s Guide](#) manual.

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: TP	PRODUCT LINE: SP
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2008
PRINTED IN U.S.A.

July 10, 2008

Rev. 14

**Agilent Technologies**

Page 1 of 1