

N5183A-06**S E R V I C E****N O T E**

Supersedes:

None

N5183A - MXG Vector Signal Generator

Serial Numbers: MY47420300 through MY47420475
MY49060001 through MY49060555
SG49060001 through SG49060088

The power supply for a range of N5183As has a higher failure rate due to a substandard part. Power Supply FAILURES in this range of N5183As will be repaired under warranty until January 1, 2011.

Parts Required:

P/N	Description	Qty.
N5180-60060	A1 Power Supply	1 each

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: MC	PRODUCT LINE: PL15
ADDITIONAL INFORMATION: This covers only Power Supply failures in the range of units described above at the customer site or at an Agilent service center.	

© AGILENT TECHNOLOGIES, INC. 2010
PRINTED IN U.S.A.

March 31, 2010

Rev. 17

**Agilent Technologies**

Page 1 of 2

Situation:

The N5183A MXG Signal Generator Power Supplies in this range may have been built with FETs that have a higher failure rate. The power supply problem has been identified and resolved. Some units within these serial numbers may have a higher power supply failure rate.

Solution/Action:

The purpose of this Service Note is to extend warranty coverage for power supply FAILURES in this range of serial numbers to January 1, 2011.