

N5230C-07**S E R V I C E N O T E**Supersedes:
none**N5230C PNA-L Series Microwave Network Analyzers****Serial Numbers:**

MY48100404 - MY48100410, MY49000867, MY49000885, MY49000912, MY49001299, MY49001375, MY49001432, MY49001433, MY49001437, MY49001438, MY49001597, MY49001606, MY49001674, MY49001682, MY49001726, MY49001742, MY49001970, MY49141037, MY49140118.

Some network analyzers may require servicing. Only serial numbers listed above are affected.

Parts Required:

(Refer to Service Note N5230C-06)

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	ON SPECIFIED FAILURE	STANDARDS LABOR: 6.0 Hours (includes 4 hours calibration)
LOCATION CATEGORY:	SERVICE CENTER	SERVICE INVENTORY: N/A USED PARTS: SCRAP
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: October 2014
Calibration Required	PRODUCT LINE: WN AUTHOR: MF	
ADDITIONAL INFORMATION:		
Service Center: please reference Service Note N5230C-06		

© AGILENT TECHNOLOGIES, INC. 2012
PRINTED IN U.S.A.

September 26, 2012

Rev. 20

**Agilent Technologies**

Situation:

Some network analyzers may require servicing. Only serial numbers listed on the previous page are affected.

Solution/Action:

Service Center personnel, please reference Service Note N5230C-06 for more detail.