

N5230C-07A

S E R V I C E N O T ESupersedes:
N5230C-07

N5230C PNA-L Series Microwave Network Analyzers

Serial Numbers:

See list at end of this Service Note.

Some network analyzers may require servicing. Only serial numbers listed are affected.**Parts Required:**

(Refer to Service Note N5230C-06A)

ADMINISTRATIVE INFORMATION

| | | | |
|--|--|---|-------------------|
| SERVICE NOTE CLASSIFICATION: | | | |
| MODIFICATION RECOMMENDED | | | |
| ACTION CATEGORY: ON SPECIFIED FAILURE | | STANDARDS LABOR: 6.0 Hours (includes 4 hours calibration) | |
| LOCATION CATEGORY: SERVICE CENTER | | SERVICE INVENTORY: N/A | USED PARTS: SCRAP |
| AVAILABILITY: PRODUCT'S SUPPORT LIFE | | NO CHARGE AVAILABLE UNTIL: October 2014 | |
| Calibration Required | | PRODUCT LINE: WN AUTHOR: MF | |
| ADDITIONAL INFORMATION: N5230C-07 created 9/21/12. N5230C-07A created 10/31/12 to revise serial numbers. | | | |
| Service Center: please reference Service Note N5230C-06A | | | |

© AGILENT TECHNOLOGIES, INC. 2012
PRINTED IN U.S.A.

October 31, 2012

Rev. 20



Situation:

Some network analyzers may require servicing. Only serial numbers listed on the previous page are affected.

Solution/Action:

Service Center personnel, please reference Service Note N5230C-06A for more detail.

Serial Numbers:

| |
|------------|
| MY48100404 |
| MY48100405 |
| MY48100406 |
| MY48100407 |
| MY48100408 |
| MY48100409 |
| MY48100410 |
| MY48100418 |
| MY48100419 |
| MY48100428 |
| MY48100435 |
| MY48100436 |
| MY48100490 |
| MY48100491 |
| MY48100494 |
| MY49000656 |
| MY49000658 |
| MY49000721 |
| MY49000866 |
| MY49000867 |
| MY49000885 |
| MY49000912 |
| MY49001256 |
| MY49001299 |
| MY49001375 |
| MY49001432 |
| MY49001433 |
| MY49001437 |
| MY49001438 |
| MY49001451 |
| MY49001452 |
| MY49001453 |
| MY49001535 |
| MY49001537 |
| MY49001597 |
| MY49001606 |
| MY49001674 |
| MY49001682 |
| MY49001726 |
| MY49001742 |
| MY49001970 |