

N7782B-01

S E R V I C E N O T E

Supersedes:
NONE

N7782B – PER Analyzer

Serial Numbers: MY48201024

Poor PER measurement due to noisy SOP values

Parts Required:

| P/N | Description | Qty. |
|-----------|----------------------|------|
| 0160-7749 | Capacitor-Fixed 22pF | 4 |

ADMINISTRATIVE INFORMATION

| | | |
|---|---|---|
| SERVICE NOTE CLASSIFICATION: | | |
| MODIFICATION RECOMMENDED | | |
| ACTION CATEGORY: | <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME | STANDARDS LABOR: 2.5 Hours (+1h for cal) |
| LOCATION CATEGORY: | <input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER | SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> Checked - OK USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> No parts exchanged |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | NO CHARGE AVAILABLE UNTIL: 31-Oct-2013 |
| <input checked="" type="checkbox"/> Calibration Required <input type="checkbox"/> Calibration NOT Required | PRODUCT LINE: 3E AUTHOR: MF | |
| ADDITIONAL INFORMATION: | | |

© AGILENT TECHNOLOGIES, INC. 2012
PRINTED IN U.S.A.

August 14, 2012

Rev. 20



Situation:

We (Agilent) have learned from a failure analysis of a defective product that there was a very small production run that shows an increased noise level at low optical input power levels.

We are offering and recommending a free-of-charge service for the identified units.

Solution/Action:

As units with the above mentioned serial numbers might be affected, please send it to your nearest Agilent service location for the hardware update which fixes the issue. Additionally we will provide complimentary commercial calibration including a respective calibration certificate. Please refer to this Service Note "N7782B-01".

In case of any further questions or to coordinate logistics to perform this service, please contact your local Agilent representative or your nearest Agilent Contact center, for details see

<http://www.home.agilent.com/agilent/morecountries.jspx> .