

## S E R V I C E N O T E

SUPERSEDES: None

**3784A Digital Transmission Analyzer**

Serial Numbers: 0000U00000 / 3117U01490

**Modification to housing for C1 & C2 power supply capacitors and change in dimension of C1 & C2.****To Be Performed By:** Agilent Personnel**Parts Required:**

Part No.	Description	Qty.
0180-3253	470 uF, 200V Capacitor	2
03780-00146	Cover, Capacitor	1

**Situation:**

Capacitors C1 & C2 (see replaceable parts section of manual - Main List) have been reduced in length by 11mm. The top cover (MP22) has been modified to accommodate the new size of capacitor

DATE: 02 March 1993

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**MODIFICATION AVAILABLE**ACTION  
CATEGORY:**AGREEABLE TIME**
☐ PERFORMANCE ENHANCEMENT  
☒ SERVICE/RELIABILITY ENHANCEMENT
LOCATION  
CATEGORY:
☐ CUSTOMER INSTALLABLE  
☐ ON-SITE  
☒ SERVICE CENTER

AVAILABLE UNTIL: Support Life

AUTHOR: SM

ENTITY: 1400

ADDITIONAL INFORMATION:

