

## S E R V I C E N O T E

SUPERSEDES: NONE

**4294A Precision Impedance Analyzer**

Serial Numbers: JP2KG00101 / JP2KG00221

**External Tests for analog circuits****To Be Performed By:** Customer Installable**Parts Required:**

P/N	Description	Quantity
04294-18006	Flexible Disk (Rev. 01.02)	1ea
5080-3949	Label "Firmware Rev 01.02"	1ea
04294-90102	F/W Installation Manual	1ea

P/N 04294-65400 "Agilent 4294A Revision 01.02 Firmware Installation Kit" contains all of the required parts. Agilent Service Center can download the firmware and Manual from CTU-Kobe's Home Page.

**Situation:**

The 4294A with firmware 01.00 or 01.01 can not support the external tests for analog circuits of the 4294A.

**Solution / Action:**

The firmware 01.02 supports the external tests for analog circuits of the 4294A. When you receive the 4294A with firmware 01.00 or 01.01, please install the firmware 01.02 into the 4294A using the Firmware Installation Kit described above.

DATE: February 2000

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 0.5 Hours
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
		USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: February 2002	
AUTHOR: KW	ENTITY: 3355	ADDITIONAL INFORMATION:	

