

SUPERSEDES:

none

HP MODEL 6012A AUTORANGING POWER SUPPLY
Serial Numbers 1946A00140 and Below
CURRENT MONITOR RESISTOR CHANGE

Current Monitor Resistor A1R20 has been changed from HP Part No. 06012-80005 to HP Part No. 06012-80006. The new value is 3.4 m Ω . If the old resistor is to be replaced by the new one, then these changes will also have to be made on the A2 control board:

1. A2R27 from 0698-6335 (900 Ω) to 0698-6341 (750 Ω).
2. A2 R8 from 0757-0413 (392 Ω) to 0757-0410 (301 Ω).

These changes compensate for the current monitor resistance change.

E/OF/WO

10/81-21/JY



FOR MORE INFORMATION, CALL YOUR LOCAL HP SALES OR SERVICE OFFICE or East (201) 265-5000 • Midwest (312) 255-9800 • South (404) 955-1500 • West (213) 970-7500 or (415) 968-9200; OR WRITE, Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304. IN EUROPE, CALL YOUR LOCAL HP SALES or SERVICE OFFICE OR WRITE, Hewlett-Packard S.A., 7, rue du Bois-du-Lan, P.O. Box, CH-1217 MEYRIN 2 - Geneva, Switzerland. IN JAPAN, Yokogawa-Hewlett-Packard Ltd., 9-1, Takakura-cho, Hachioji-shi, Tokyo, Japan 192.