

S E R V I C E N O T E

SUPERSEDES: NONE

E3101A: 4071A Semiconductor Parametric Tester

Serial Numbers: JP20D00473,474,475,477,478,479,488,490,491,492
 JP30D00501,502,504,505,509,510

17-inch monitor cannot be fixed on the rack mount kit.

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N	Description	Quantity
E3160-00185	Support shelf	1

Situation:

Because of the monitor (HP D8900 HP 75) design change, the 17-inch monitor cannot be fixed on the E3101A option 020 rack mount kit. When you tighten the belt which fixes the 17-inch monitor, the 17-inch monitor moves ahead.

Solution / Action:

Replace the old support shelf (P/N E3160-00181) with the new support shelf (P/N E3160-00185). The new support shelf fits the both old and new 17-inch monitor (HP D8900 HP75).

After replacing the support shelf, check the stability of the monitor.

Necessary parts are supplied from the ATLS.

DATE: July 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input checked="" type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 1.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: SY	ENTITY: 3300	AGILENT RESPONSIBLE UNTIL: July 2001	
		ADDITIONAL INFORMATION:	

