

MODIFICATION RECOMMENDED

# MSO7104A-01

# S E R V I C E N O T E

Supersedes:  
NONE

## MSO/DSO7000A Series InfiniiVision Oscilloscope

Serial Numbers: MY48250001 or below and SG48250001 or below

**New Cap-Strap Handles are replacing older ones that might crack with use.**

**Part number 5041-9607 replaces part number 5042-6805.**

**Parts Required:**

P/N	Description	Qty.
5041-9607	Cap-Strap Handle	2

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 0.5 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: (1-Jun-2010)	
AUTHOR:	EG	PRODUCT LINE: PL1A	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2008  
PRINTED IN U.S.A.

September 30, 2008

Rev. 15



**Situation:**

Old Cap-Strap Handles (P/N 5042-6805) may crack.

**Solution/Action:**

Replace with new Cap-Strap Handles, P/N 5041-9607.