| | | | | | | | | Ε | 826 | 7D- | 25 |
|---|---|---|---|---|---|---|--|---|-----|-----|----|
| S | Ε | R | V | I | C | Ε | | Ν | 0 | Т | Ε |

Supersedes: None

E8267D Digital Signal Generator

Serial Numbers: All

When No Trouble Found (NTF) is encountered, contact the division prior to sending the unit back to the customer. Please send an e-mail to the support node, SUPPORT, MCD (A-Sonoma, exgen1).

Parts Required:
P/N Description Qty.
None

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: | | | | | | | | | |
|------------------------------|------------------|--|--|--|--|--|--|--|--|
| INFORMATION ONLY | | | | | | | | | |
| INTERNAL ONLY DOCUMENT | | | | | | | | | |
| AUTHOR: SN | PRODUCT LINE: 15 | | | | | | | | |
| ADDITIONAL INFORMATION: | | | | | | | | | |
| | | | | | | | | | |

© AGILENT TECHNOLOGIES, INC. 2011 PRINTED IN U.S.A.

Agilent Technologies

Page 1 of 2

December 6, 2011

Rev. 18

Page 2 of 2 E8267D-25

Situation:

Every month, the division reviews the Reliability Performance for the E8267D product. From the CCAFR data, we observe many cases where a failure is reported by the customers, but closed as NTF (failures are not able to be duplicated). Please contact the division, so that we can understand the problem in more detail before the instrument is sent back to the customers.

Solution/Action:

None